



Оправки силовые фрезерные




| Обозначение    | ISO   | d<br>мм | A<br>мм | D<br>мм |
|----------------|-------|---------|---------|---------|
| • 240.090.MC20 | BT 40 | 20      | 90      | 53      |
| • 240.090.MC25 | BT 40 | 25      | 90      | 63      |
| • 240.090.MC32 | BT 40 | 32      | 90      | 68      |
| • 250.095.MC20 | BT 50 | 20      | 95      | 53      |
| • 250.095.MC25 | BT 50 | 25      | 95      | 63      |
| • 250.090.MC32 | BT 50 | 32      | 90      | 68      |

Комплектующие

|                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                      |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
|  |  |  |  |  |
| Втулка МСС..<br>стр. 681                                                            | Втулка МС..<br>стр. 683                                                             | Штревель<br>стр. 693                                                                | Набор<br>—                                                                          | Ключ<br>—                                                                            |



Оправки с креплением WELDON DIN 1835-B



| Обозначение    | ISO   | d (H4)<br>мм | A<br>мм | D<br>мм | Форма |
|----------------|-------|--------------|---------|---------|-------|
| • 230.050.WB06 | BT 30 | 6            | 50      | 25      | AD    |
| • 230.050.WB08 | BT 30 | 8            | 50      | 28      | AD    |
| • 230.050.WB10 | BT 30 | 10           | 50      | 35      | AD    |
| • 230.050.WB12 | BT 30 | 12           | 50      | 42      | AD    |
| • 230.050.WB14 | BT 30 | 14           | 50      | 44      | AD    |
| • 230.063.WB16 | BT 30 | 16           | 63      | 48      | AD    |
| • 230.063.WB18 | BT 30 | 18           | 63      | 50      | AD    |
| • 230.063.WB20 | BT 30 | 20           | 63      | 52      | AD    |
| • 240.035.WB16 | BT 40 | 16           | 35      | 45      | AD/B  |
| • 240.035.WB20 | BT 40 | 20           | 35      | 45      | AD/B  |
| • 240.035.WB25 | BT 40 | 25           | 35      | 55      | AD/B  |
| • 240.065.WB32 | BT 40 | 32           | 65      | 50      | AD/B  |
| • 240.050.WB06 | BT 40 | 6            | 50      | 25      | AD/B  |
| • 240.050.WB08 | BT 40 | 8            | 50      | 28      | AD/B  |
| • 240.050.WB10 | BT 40 | 10           | 50      | 35      | AD/B  |
| • 240.063.WB12 | BT 40 | 12           | 63      | 42      | AD/B  |
| • 240.063.WB14 | BT 40 | 14           | 63      | 44      | AD/B  |
| • 240.063.WB16 | BT 40 | 16           | 63      | 48      | AD/B  |
| • 240.063.WB18 | BT 40 | 18           | 63      | 50      | AD/B  |
| • 240.063.WB20 | BT 40 | 20           | 63      | 52      | AD/B  |