





(A) X4	
(B) X2	
(C) X2	
(D) X2	
(E) X2	
(F) X4	
(G) X1	
(H) X20	 M8*35mm
(I) X8	 M8*30mm
(J) X28	
(K) X28	
(L) X28	
(P) X1	
(N) X1	



Diagram showing the assembly of a diamond-shaped panel. A circular inset shows a close-up of a bracket (A) being attached to the panel with a screw (H).


Diagram showing the assembly of a rectangular panel. A circular inset shows a close-up of a bracket (B) being attached to the panel with a screw (H). Another circular inset shows a close-up of a bracket (C) being attached to the panel with a screw (H).

Diagram showing the assembly of a rectangular panel. A circular inset shows a close-up of a bracket (F) being attached to the panel with a screw (H). Another circular inset shows a close-up of a bracket (F) being attached to the panel with a screw (H).

Diagram showing the assembly of a rectangular panel. A circular inset shows a close-up of a bracket (F) being attached to the panel with a screw (H). Another circular inset shows a close-up of a bracket (F) being attached to the panel with a screw (H).





①×2 	②×2 
③×2  L	④×2  R
⑤×4 	⑥×4 
Ⓐ×4  30mm	Ⓑ×8  40mm
Ⓒ×8  30mm	Ⓓ×24  16mm
Ⓔ×4 	Ⓕ×24 
Ⓖ×4 	Ⓗ×4 
Ⓘ×2 	Ⓙ×1 

