



























BST-R2304



BST-R2305






A1  X1	A2  X1	A3  X1	A4  X2	A5  X2	A6  X2
A7  X2	A8  X1	A9  X1	A10  X1	A11  X1	A12  X4
A13  X1	A14  X2	A15  X2	A16  X1	A17  X1	A18  X1
A19  X2	A20  X1	A21  X4	A22  X1	A23  L=1.5M X1	A24  X2
A25  X8	A26  X4	A27  X10	A28  X2	A29  X2	A30  X1
A31  X1	A32  X1	 ST4X10=20	 M4X25= 2	 ST4x20=8	 ST4X16=18
 Ø2.8					






A20




A3

A19



ST4X10=8



A25




ST4X16




Ø M2.8


A25




ST4X16




A14




A8




A30




A32




A18




A15




A14



A30




A10




A23

A22



A17



A23

