





**HX** SERIE


Exploded views  
Bauzeichnungen

**RS ROBLAND®**  
MADE IN BELGIUM




	BENAMING	STUKNUMMER	EHX0001	REVISE
	DATUM			
	12/10/10			
	>SCHAAFUNIT <			
				6






<b>ROBLAND</b>	DATUM 12/10/10	BENAMING >LETTERBOX<	STUKNUMMER EHX0004	REVISE 6
----------------	-------------------	-------------------------	-----------------------	-------------



















REVISE

STUKNUMMER

EHX0014

0

BENAMING

&gt;FRAME HX-TZ&lt;


DATUM

07/03/12

ROBLAND









STUKNUMMER	EHX0032	REVISIE
BENAMING	wielstel HX combiné 260/310	0
DATUM		

**ROBLAND**




STUKNUMMER	EHX0033	REVISIE	0
BENAMING	wielstel HX TZ	DATUM	












<b>ROBLAND</b>	DATUM 05/07/11	BENAMING >OPTIE STEUN LOOPWAGEN<	STUKNUMMER ENX012	REVISE 4
----------------	-------------------	-------------------------------------	----------------------	-------------




REVISIE	STUKNUMMER	BENAMING	DATUM	ROBLAND
4	ENX0014	>HOEKVERSTEK<	12/10/10	











STUKNUMMER	ENX0032	BENAMING	>LOOPWAGEN 2050<
REVISION	11	DATUM	02/04/15






<b>ROBLAND</b>	<b>PENNEPLAAT</b>	<b>ENX0033</b>
<b>DATUM</b>	<b>BENAMING</b>	<b>STUKNUMMER</b>
<b>2</b>	<b>2</b>	<b>REVISIE</b>






HX 1ph 2dir 1vit NCE


HX0987




HXZ 1dir 3ph CE

HX0993.0







HX 1dir 3ph CE

HX0998











**Robland**

Kolvestraat 44  
8000 Brugge - Belgium  
Tel.: +32 50 458 925  
Fax: +32 50 458 927  
[www.robland.com](http://www.robland.com)